

## CAMPAIGN LAUNCH STATUS

### NEW SAFETY RECALLS N494 – RANGE ROVER SPORT



#### SAFETY COMPLIANCE RECALL N494 20-21MY RANGE ROVER SPORT

AFFECTED MODELS	20-21MY Range Rover Sport
VOLUME AFFECTED	11,950 USA
REPAIR	Affected vehicles require a software update to the tire pressure module to correct TPMS pressure values used for low pressure warnings to customers. Repair requires manual patch download to each Pathfinder tool..
REPAIR TIME	0.2 hrs + drive in/out
CAMPAIGN LAUNCH	Target by October 19 <sup>th</sup> 2020
Notes	Retailers were notified by aftersales bulletin NAS20.10.008 on Oct 8 <sup>th</sup> , 2020. Refer to BBSS for c 1000 unsold vehicles at retailers