

# Part 573 Safety Recall Report

## 20V-612

**Manufacturer Name :** Suzuki Motor of America, Inc.**Submission Date :** SEP 30, 2020**NHTSA Recall No. :** 20V-612**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Suzuki Motor of America, Inc.

Address : 3251 East Imperial Highway  
Brea CA 92821-6795

Company phone : 714-996-7040

**Population :**

Number of potentially involved : 2,040

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Suzuki GSX250R

Vehicle Type : MOTORCYCLES

Body Style : ALL

Power Train : GAS

**Descriptive Information :** The recall population is based on production records. Vehicles not included in the recall population were equipped with a redesigned headlamp assembly that included a revised headlamp bulb attachment system.

Production Dates : MAR 25, 2017 - MAY 25, 2017

VIN Range 1 : Begin : LC6DN11A0J1100008 End : LC6DN11A2J1102374

☐ Not sequential**Description of Defect :**

Description of the Defect : The low and/or high beam headlamp bulb filament may break prematurely.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Sudden loss of headlamp illumination could reduce operator visibility and/or conspicuity, increasing the risk of a crash.

**Description of the Cause :** Suzuki has not yet determined the root cause of this condition.

**Identification of Any Warning** NR  
that can Occur :

**Involved Components :**

Component Name 1 : Headlamp Assembly

Component Description : Vehicle headlamp

Component Part Number : 35100-20K30

### Supplier Identification :

#### Component Manufacturer

Name : Chongqing JiaLi jianqiao lamps Co.,LT

Address : 11#, Chuangye Road

ShuangFu Street Jiangjin District, ChongQing FOREIGN STATES

Country : China

### Chronology :

The chronology of principal events is attached as a separate document.

### Description of Remedy :

Description of Remedy Program : Suzuki has not yet determined a remedy. Suzuki will notify NHTSA through an amended Part 573 report when a remedy has been determined.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

### Recall Schedule :

Description of Recall Schedule : Suzuki has not yet decided a recall notification schedule, but will mail owner notification letters no more than 60 days from the date of submission of this report. Suzuki will notify NHTSA through an amended Part 573 report when a notification schedule has been decided.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported