



SUZUKI MOTOR CORPORATION

Motorcycle Service Group
Overseas Service Department
8686, Miyakoda, Kita, Hamamatsu, Shizuoka, Japan Zip 431-2102
Tel: 81-53-528-8118, Fax: 81-53-528-8141

Page 1 of 1
Date Sep. 25, 2020
Our ref. FF-200925

To : SUZUKI MOTOR OF AMERICA, INC.
Attn. : Managing Director
Service Director or Manager

SUBJECT: GSX250R L7 Headlamp Bulb Market Action

Dear Sirs and Madams,

We regret to inform you that the Headlamp Bulb of GSX250R L7 may go off in a short time. We would like to request you to take the following actions.

1. Condition

The filament of the headlamp bulb may be broken in a short time and headlamp may go off during driving.

2. Affected Vehicles Information

- (1) Model : GSX250R L7 produced in China
- (2) Production Period : From Mar. 25 2017 to May. 25 2017
- (3) Vehicles : 2,040 units

3. Action

Please notify this information to your authority as needed. We will announce further information upon determination of its root cause and corrective action. Please prematurely procure customer information for getting ready to send a notification, however, continue to hold sending until next decision is made.

We are very sorry for causing inconvenience to you. Your cooperation and assistance will be highly appreciated. If you have any question, please don't hesitate to contact us anytime.

Very truly yours,


Shinji Ishikawa
Department General Manager
Overseas Service Department
SUZUKI MOTOR CORPORATION

Attachment: ANNEX1_America_VIN_List