

Automobili Lamborghini S.p.A.

Vs. riferimento Vs. data Oggetto Data

Via Modena, 12 I-40019 Sant'Agata Bolognese Telefono +39 051-681 76 11 Telefax +39 051-681 76 44

Front frame replacement Lamborghini Aventador SVJ MY 20/21 S. Agata Bolognese, Italy dated October 29, 2020

Dear valued Lamborghini Sales and Service Manager,

In the course of continuous product monitoring and internal tests, Automobili Lamborghini S.p.A. has determined the possibility that a few Lamborghini Aventador SVJ does not fully meet the requirements of Vehicle Safety Standards.

On the affected vehicles, the front frame suspension arm anchor bolt torque could be insufficient due to potentially damaged aluminum frame threads caused by an improper rework tool that may have been used by the parts supplier during manufacturing.

If this condition is present in the vehicle, the suspension arm joint could be affected and it may collapse resulting in loss of control of the vehicle, increasing the risk of a crash and injury to the occupants.

For all the reasons listed above, these vehicles must therefore be reworked. The repair instructions are now available on the HUB section "Service and Recall Campaigns".

In order to further support you in answering questions to your customers, we are attaching the FAQ (Frequent Asked Question) you must follow to. Since these activities are extremely important, we are confident you will make every effort to ensure that the vehicles are repaired in the shortest time possible.

Capitale Sociale € 130.000.000 R.E.A. Bologna 259882 Codice Fiscale 03049840378 Partita I.V.A IT00591801204 A socio unico Società del Gruppo Audi



The significant dates for this recall are here below listed:

• Campaign launch in LIASS October 30th;

Please contact your Area Manager for any further information.

thall. le

Paolo Gabrielli Head of After Sales