

U.S. Department of Transportation

National Highway Traffic Safety Administration

November 16, 2020

Ms. Helen Riehle Safety Integrity and Recall Manager BMW of North America, LLC 300 Chestnut Ridge Road Woodcliff Lake, NJ 07677 NEF-150DM 20V-666

1200 New Jersey Avenue SE Washington, DC 20590

Subject: Fuel Injector Installed Without Damping Component

Dear Ms. Riehle:

This letter serves to acknowledge BMW of North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

BMW/M2/2020-2021 BMW/M4/2020

Mfr's Report Date: October 29, 2020

NHTSA Campaign Number: 20V-666

Components:

FUEL SYSTEM, GASOLINE: FUEL INJECTION SYSTEM

Potential Number of Units Affected: 21

Problem Description:

BMW of North America, LLC (BMW) is recalling certain 2020-2021 M2 Coupe and 2020 M4 Coupe vehicles. Fuel injectors may have been installed without a damping component which is used to reduce vibration. If a damping component is not present, vibration will increase at the connection between the fuel line and the fuel rail, which over time, can result in damage at the connection.

Consequence:

A damaged connection between the fuel line and the fuel rail could lead to a fuel leak and, in the presence of an ignition source, increase the risk of a fire.

Remedy:

BMW will notify owners, and dealers will inspect the fuel injectors and if a damping component is missing, the injectors and the fuel rail will be replaced, free of charge. The recall is expected to begin December 21, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be DeMara Magruder who may be reached by phone at (202) 366-8538, or by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

