

Part 573 Safety Recall Report

20V-667

Manufacturer Name : Jayco, Inc.**Submission Date :** OCT 29, 2020**NHTSA Recall No. :** 20V-667**Manufacturer Recall No. :** 9903527**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2020-2021 Class A Motorhome Alante, Vision, Vision XL, Precept, Precept Prestige

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : Production records of units produced prior to ECN change.

2020 Alante L1AF0088-0180 AS0120-137 AU0130-0144

2021 Alante M1AF4051-4060 AS4051-4065 AU4051-4075 AV4051-4064 M1AS9000
AU-9000

2020 Precept L1UG0241-0260 UL0205-0231

2021 Precept M1UA9000-9001 UL9000-9021 UV9000

2021 Precept Prestige M1DH9000-9003 DU9000-9003

2020 Vision L1AF8088-8097 AS8098-8113 AU8087-8099

2021 Vision M1AF8051-8065 AS8051-8065 AU8051-8075 AV8051-8054

2020 Vision XL M1UB8051-8058

2021 Vision XL M1UG8051-8063 9000-9025

Production Dates : MAR 03, 2020 - AUG 04, 2020

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : Engine covers installed on some F-53 chassis did not contain appropriate insulation.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Under certain operation conditions, and wo the insulation material the interior surface temperatures could exceed desirable levels, exposing occupants to unreasonable risk of injury

Description of the Cause : Engineering change notice filed on 7-1-20 changed the engine cover

configuration to add insulation material for the 2021 MY. A delay in tooling needed for the formed insulation materials caused some of the first 2021 units to have no insulation material.

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR
Component Description : NR
Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR
Address : NR
NR
Country : NR

Chronology :

8-24-20 Incident filed to report engine cover hot to the touch - Elevated to CPAC for research
9-2 CPAC continued research with Engineering and Operations
9-10 Request for testing by R&D submitted -
9-24- SSC reviewed situation and asked that additional testing / research be conducted prior to their decision how to proceed - testing continued through 10-2
10-22 SSC reviewed all details again and testing then agreed that a safety recall is required

Description of Remedy :

Description of Remedy Program : Jayco Dealer will remove and disable the engine cover to allow the addition of the insulation insert - reassemble engine cover and install foam seal on the outer edge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : All units produced after 8-4-20 contain the insulation insert.

Recall Schedule :

Description of Recall Schedule : Jayco is prepared to release recall.

Planned Dealer Notification Date : NOV 20, 2020 - NOV 20, 2020

Planned Owner Notification Date : NOV 20, 2020 - NOV 20, 2020

* NR - Not Reported