



April, 2021

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2021 F-650 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** 20S66 - TRANSMISSION OIL COOLER LINE INSPECTION

**What is the issue?** On your vehicle, it is possible one of the Transmission Oil Cooler Lines may have been improperly installed, which may subsequently come in contact with the Air Conditioning Pulley. This may result in a leak.

Leaking transmission fluid can result in erratic shifting, missed gear shifting, vibration, shudder and check engine light illumination. Leaking transmission fluid in this location could also come in contact with the engine exhaust, creating a fire risk.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: [owner.ford.com](http://owner.ford.com).

Thank you for your attention to this very important matter.

Abril de, 2021

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2021 F-650 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** 20S66 - INSPECCIÓN DE LA TUBERÍA DEL ENFRIADOR DE ACEITE DE LA TRANSMISIÓN

**¿Cuál es el problema?** Es posible que una de las tuberías del enfriador de aceite de la transmisión de su vehículo se haya instalado incorrectamente, lo cual, con el tiempo, podría generar contacto con la polea del aire acondicionado. Esto podría provocar una fuga.

Una fuga del fluido de la transmisión podría ocasionar cambios erráticos, ausencia de cambios de velocidad, vibración, trepidación y el encendido de la luz de revisión del motor. Una fuga de fluido de la transmisión en esta ubicación también podría provocar contacto con el escape del motor y crear un riesgo de incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [owner.ford.com](http://owner.ford.com).

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

D / 0023 / 000000000000087 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

