



April, 2021

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2020 Aviator has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **20S65 - DRIVE SHAFT WELD SEAM**

**What is the issue?** On your vehicle, the rear driveshaft may have not been welded properly during production. Vehicles affected may experience noise and vibration while driving.

Affected driveshafts may deform and potentially contact the fuel tank, increasing the risk of fuel leaks and/or fire. Inadequately welded drive shafts may also lose the mechanical connection between the transfer case and rear axle which may result in unintended vehicle movement and/or loss of motive power.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: [owner.lincoln.com](http://owner.lincoln.com).

Thank you for your attention to this very important matter.

Abril de, 2021

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2020 Aviator las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **20S65 - UNIÓN DE SOLDADURA DE LA FLECHA DE MANDO**

**¿Cuál es el problema?** Es posible que la flecha de mando trasera de su vehículo no se haya soldado correctamente en producción. Los vehículos afectados podrían experimentar ruido y vibración al manejar.

Las flechas de mando afectadas podrían deformar y, posiblemente, entrar en contacto con el tanque de combustible, lo cual aumenta el riesgo de fuga de combustible o incendio. Las flechas de mando soldadas incorrectamente también podrían perder la conexión mecánica entre la caja de transferencia y el eje trasero, lo cual podría generar un movimiento involuntario del vehículo o pérdida de potencia motriz.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [owner.lincoln.com](http://owner.lincoln.com).

Gracias por su atención en este asunto sumamente importante.



THE LINCOLN MOTOR COMPANY

P.O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

D / 0053 / 000000000000081 / A



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST  
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

