# Part 573 Safety Recall Report

Manufacturer Name :Jaguar Land Rover North America, LLCSubmission Date :NOV 10, 2020NHTSA Recall No. :20V-694Manufacturer Recall No. :N400



**Population :** 

20V-694

#### Manufacturer Information :

Manufacturer Name :Jaguar Land Rover North America, LLCNumber of potentially involved :11,084Address :100 Jaguar Land Rover WayEstimated percentage with defect :100 %Mahwah NJ 07495Address :8188500100 %

### Vehicle Information :

Vehicle 1:	2019-2020 LAND ROVER DISCOVERY
Vehicle Type :	LIGHT VEHICLES
Body Style :	SUV
Power Train :	NR
Descriptive Information :	A concern has been identified with certain 2019 and 2020 Model Year Discovery vehicles, built at the Nitra assembly plant, where due to insufficient contact of the battery ground stud to the chassis, the vehicle may exhibit various electrical faults. The vehicle could cut out while in motion and may lose all electrical power. 11,084 Discovery vehicles in the United States and Federalized Territories. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for vehicles affected were determined by specific model type and specification 2019 and 2020MY Discovery vehicles built from September 21, 2018 to August 31, 2020.
Production Dates :	SEP 21, 2018 - AUG 31, 2020
VIN Range 1:	Begin :    SALRR2RV6K2400085    End :    SALRG2RV9K2414715    Image: Not sequential
VIN Range 2:	Begin :    SALRT2RV6L2414734    End :    SALRR2RV1L2443301    Image: Not sequential

## **Description of Defect :**

Description of the Defect :	A concern has been identified with certain 2019 and 2020 Model Year Discovery vehicles, built at the Nitra assembly plant, where due to insufficient contact of the battery ground stud to the chassis, the vehicle may exhibit various electrical faults. The vehicle could cut out while in motion and may lose all electrical power.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Vehicle cut out while in motion and loss of exterior lighting without warning to the driver could lead to an increased risk of an accident.
Description of the Cause :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

**20V-694** 

Page 2

Identification of Any Warning NR that can Occur :

#### **Involved Components :**

Component Name 1 : Ground Stud Component Description : Ground Stud

Component Part Number : NR

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Jaguar Land Rover Limited

Address: Abbey Road Whitley, Conventry FOREIGN STATES CV3 4LF Country: United Kingdom

#### **Chronology**:

See file "Recall N400 Chronology".

#### **Description of Remedy :**

Description of Remedy Program :Retailers will replace the ground stud with a modified part. There will be<br/>no charge to owners for this repair. The vehicles will be covered under<br/>Jaguar Land Rover's new vehicle warranty program. Customers who have<br/>paid for a repair of this defect will be reimbursed by the Jaguar Land Rover<br/>reimbursement plan, subject to terms and conditions.How Remedy Component Differs<br/>from Recalled ComponentNRIdentify How/When Recall Condition<br/>was Corrected in Production :NR

The information contained in this report was submitted pursuant to 49 CFR §573

# Recall Schedule : Description of Recall Schedule : Distribution of owner notification letters will occur on or before January 8, 2021. Notifications to retailers will occur on November 24, 2020. Planned Dealer Notification Date : NOV 24, 2020 - NOV 24, 2020 Planned Owner Notification Date : JAN 08, 2021 - JAN 08, 2021

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573