

CAMPAIGN LAUNCH STATUS

N400 RECALL - BATTERY GROUND STUD - 19 & 20MY DISCOVERY



SAFETY RECALL N400

AFFECTED MODELS

2019-2020 L462 Discovery existing CSP Service Action to be superseded by a safety recall with significantly larger population

VOLUME AFFECTED

11,084 USA

REPAIR

The battery cable ground stud may be loose in the body and needs to be replaced. Insufficient ground contact may lead to intermittent operation of electrical equipment

REPAIR TIME

0.2 hrs + Drive in/out

CAMPAIGN LAUNCH

Target : 12/09/2020

Notes

Retailer Notification and stop sale Nov 24th, 2020 - Bulletin NAS20.11.018. For the recall, replacement ground studs will now be supplied through Land Rover Parts under a JLR part number.