

CAMPAIGN LAUNCH STATUS

N400 RECALL - BATTERY GROUND STUD - 19 & 20MY DISCOVERY



SAFETY RECALL N400	
AFFECTED MODELS	2019-2020 L462 Discovery existing CSP Service Action to be superseded by a safety recall with significantly larger population.
VOLUME AFFECTED	11,084 USA 740 CAN
REPAIR	The battery cable ground stud may be loose in the body and needs to be replaced. Insufficient ground contact may lead to intermittent operation of electrical equipment.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	Target : 12/09/2020
Notes	Retailer Notification and stop sale Nov 24 th 2020 - Bulletin NAS20.11.018. For the recall, replacement ground studs will now be supplied through Land Rover Parts under a JLR part number. New Warranty option codes.