



April, 2021

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2020 Explorer has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: 20S68 - NINETEEN GALLON FUEL TANK IMPROPER WELD

What is the issue? On your vehicle, it may be possible, the inlet check valve was not fully welded to the fuel tank shell. This may result in a check engine light for a small evaporative emissions leak and could progress into a fuel odor condition.

An incomplete weld securing the inlet check valve to the fuel tank shell could result in a substantial fuel leak during a crash, increasing the risk of fire.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: owner.ford.com.

Thank you for your attention to this very important matter.

Abril de, 2021

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2020 Explorer las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: 20S68 - SOLDADURA INCORRECTA DEL TANQUE DE COMBUSTIBLE DE DIECINUEVE GALONES

¿Cuál es el problema? Es posible que la válvula unidireccional de admisión de su vehículo no se haya soldado totalmente al tambor del tanque de combustible. Esto podría provocar el encendido de la luz de revisión del motor por una pequeña fuga de emisiones evaporativas que, posteriormente, podría generar una condición de olor de combustible.

Una soldadura incompleta que fija la válvula unidireccional de admisión al tambor del tanque de combustible podría provocar una fuga considerable de combustible en caso de choque, lo cual aumenta el riesgo de sufrir un incendio.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: owner.ford.com.

Gracias por su atenciic en este asunto sumamente importante.



P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

D / 0096 / 000000000000093 / A



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

