

[Next Unread Message](#)

View Message

Sent on	03	05	2021	Expires on	04	05	2021
From	AHM Parts and Service Division						
Subject	2013-15 Accord Driveshaft Inspection - Parts Return Instructions						

PRIORITY/ACTION REQUIRED

To: Honda Parts & Service Managers

From: Warranty Parts Inspection

Effective immediately, Dealers that replace driveshafts under Service Bulletin 20-125 are not required to return these parts to Warranty Parts Inspection (WPI) in Raymond, OH.

Please note that this request applies to this Service Bulletin 20-125 and the part numbers listed below only.

- 44305-T2A-A21 Right Driveshaft Assembly (2015)
- 44306-T2A-A21 Left Driveshaft Assembly (2015)
- 44305-T2A-010 Right Driveshaft Assembly (2013-2014)
- 44306-T2A-010 Left Driveshaft Assembly (2013-2014)

If you have questions about the return requirements, please contact the WPI Administrative Office at 937 642-2737.