

[Next Unread Message](#)**View Message**

Sent on	05	07	2021	Expires on	08	04	2021
----------------	----	----	------	-------------------	----	----	------

From	Parts and Service Division
-------------	----------------------------

Subject	2009-13 and 2007-08 Fit Driveshaft Inspection - Parts Return Instructions
----------------	---

PRIORITY/ACTION REQUIRED

To: Honda Parts & Service Managers

From: Warranty Parts Inspection

Effective immediately, Dealers that replace driveshafts under Service Bulletins 21-009 (2009-13 Fit) and 21-042 (2007-08 Fit) are not required to return these parts to Warranty Parts Inspection (WPI) in Raymond, OH.

Please note that this request applies to these Service Bulletins 21-009 and 21-042 and the part numbers listed below only.

- 44306-TK6-A01 Left Driveshaft Assembly (2009-13 Fit with A/T)
- 44305-TK6-A01 Right Driveshaft Assembly (2009-13 Fit with A/T)
- 44305-TF0-N20 Right Driveshaft Assembly (2009-13 Fit with M/T)
- 44306-SLN-L00 Left Driveshaft Assembly (2007-08 Fit)
- 44305-SLN-L00 (Right Driveshaft Assembly (2007-08 Fit)

If you have questions about the return requirements, please contact the WPI Administrative Office at 937 642-2737.