

December 17, 2020

Version 2

Safety Recall: 2013-15 ILX and 2013 ILX Hybrid Driveshaft Failure

Supersedes 20-051, dated December 11, 2020, to revise the information highlighted in yellow.

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2013-15	ILX	AT models only	Check the iN VIN status for eligibility.
2013	ILX Hybrid	CVT models only	Check the iN VIN status for eligibility.

REVISION SUMMARY

The BACKGROUND was revised to provide an update on affected VIN population.

BACKGROUND

Due to improper manufacturing, the paint on the driveshaft may peel and chip over time, exposing the bare metal and potentially causing it to corrode. A corroded driveshaft can potentially break during high torque conditions rendering the vehicle unmovable, or allow the vehicle to roll while in Park, which can increase the potential of a crash or injury.

The affected VIN population for this recall has been determined. All **unaffected** VINs have been marked **closed (C)** for service bulletin 20-051 in the iN VIN status inquiry. Unaffected VINs in your dealer inventory are no longer on **STOP SALE**. Make sure to notify any clients of unaffected vehicles who were previously told their vehicle may be subject to this safety recall.

All **affected** VINs are **OPEN** in the iN VIN status inquiry, and any affected VINs in your dealer inventory are still on **STOP SALE**.

This bulletin will be updated with the repair information once the parts information is available.

END

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.