

CAMPAIGN LAUNCH STATUS

N523 RECALL 20MY EVOQUE 2nd ROW SEAT BELTS.



SAFETY RECALL N523 - L551 2nd ROW SEAT BELTS – INCORRECT SERVICE PART INSTALLED

AFFECTED MODELS	20MY Range Rover Evoque
VOLUME AFFECTED	13 USA
REPAIR	Affected vehicles have, during a previous service repair, been fitted with 2 nd row seat belts that do not meet USA FMVSS standards. Seat belt part numbers are to be inspected and any non-NAS parts will be replaced.
REPAIR TIME	Est. between 0.2 and 0.8 hrs + Drive in/out
CAMPAIGN LAUNCH	Target: February 16th, 2021
Notes	Retailer Notification January 7 th , 2021 by Aftersales Bulletin NAS21.01.003 . One unit is unsold.. Interim customer notification to be mailed by February 12th. A 2 nd mailing will follow before Feb 28 th



PRINTED COPIES ARE UNCONTROLLED