

CAMPAIGN LAUNCH STATUS

N523 RECALL 20MY EVOQUE – 2ND ROW SEAT BELTS



SAFETY RECALL N523 - L551 2ND ROW SEAT BELTS – INCORRECT SERVICE PART

AFFECTED MODELS

20MY Range Rover Evoque

VOLUME AFFECTED

13 USA

REPAIR

Affected vehicles have, during a previous service repair been fitted with 2nd row seat belts that do not meet USA FMVSS standards. Seat belt part numbers are to be inspected and any non-NAS parts will be replaced.

REPAIR TIME

Est. between 0.2 and 0.8 hrs + Drive in/out

CAMPAIGN LAUNCH

Target: January 28th, 2021

Notes

Retailer Notification January 7th, 2021 by Aftersales Bulletin.
One unsold unit



PRINTED COPIES ARE UNCONTROLLED