

CAMPAIGN LAUNCH STATUS

N523 RECALL 20MY EVOQUE – 2ND ROW SEAT BELTS



SAFETY RECALL N523 - L551 2 nd ROW SEAT BELTS – INCORRECT SERVICE PART INSTALLED		SAFETY RECALL N524 - L551 FRONT SEAT COVER MATERIAL		UPDATE PRIOR TO SALE N544 - L551 L550 ELECTRONIC PARK BRAKE NOT AVAILABLE WARNING	
AFFECTED MODELS	20MY Range Rover Evoque	AFFECTED MODELS	20MY Range Rover Evoque	AFFECTED MODELS	21MY Range Rover Evoque and Discovery Sport
VOLUME AFFECTED	13 USA	VOLUME AFFECTED	66 USA 6 CAN	VOLUME AFFECTED	32 USA 1 CAN
REPAIR	Affected vehicles have, during a previous service repair, been fitted with 2 nd row seat belts that do not meet USA FMVSS standards. Seat belt part numbers are to be inspected and any non-NAS parts will be replaced.	REPAIR	Affected vehicles have been built with front seat cover material that does not conform with FMVSS/CMVSS flammability safety standard. Seat covers will be replaced with conforming product.	REPAIR	On certain 2021 model year Discovery Sport and Range Rover Evoque vehicles, when the vehicle ignition is switched off, the EPB will not automatically apply as expected. The vehicles will require the customer feature to be enabled using the ABS ECU functions menu in Pathfinder
REPAIR TIME	Est. between 0.2 and 0.8 hrs + Drive in/out	REPAIR TIME	Est 0.8hrs+Drive in/out	REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	Revised Target: February 5th, 2021	CAMPAIGN LAUNCH	Target: February 15 th , 2021	CAMPAIGN LAUNCH	Target February 4 th , 2021
Notes	Retailer Notification January 7 th , 2021 by Aftersales Bulletin NAS21.01.003 . Launch has been deferred due to parts delivery delays. Customer notification must be mailed by February 12 th	Notes	Retailer Notification by Aftersales Bulletin NAS20.01.005 on January 7 th , 2021. Three units are unsold. Interim customer notification must be mailed by February 12 th .	Notes	28 units are in retailer inventory. The repair is currently published in SSM 75204