

## CAMPAIGN LAUNCH STATUS

### N524 RECALL - FRONT SEAT SQUAB COVER MATERIAL



#### SAFETY RECALL N524 - L551 FRONT SEAT COVER MATERIAL

AFFECTED MODELS	20MY Range Rover Evoque
VOLUME AFFECTED	66 USA 6 CAN
REPAIR	Affected vehicles have been built with front seat Dinamica cloth material that does not conform with FMVSS/CMVSS flammability safety standards . Seat covers will be replaced with conforming product.
REPAIR TIME	Est 0.8hrs+Drive in/out
CAMPAIGN LAUNCH	Target: February 15th, 2021
Notes	Retailer Notification by Aftersales Bulletin NAS20.01.005 on January 7 <sup>th</sup> , 2021. Three units are unsold. Interim customer notification to be mailed by February 12th with a second mailing to follow late February.



PRINTED COPIES ARE UNCONTROLLED