

U.S. Department of Transportation

National Highway Traffic Safety Administration

January 4, 2021

Mr. Brad Franklin Government Relations Manager Yamaha Motor Corporation, USA 6555 Katella Avenue Cypress, CA 90630

Subject: Transmission Second Gear Can Break

Dear Mr. Franklin:

This letter serves to acknowledge Yamaha Motor Corporation, USA's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

YAMAHA/FJR1300/2016-2020

Mfr's Report Date: December 28, 2020

NHTSA Campaign Number: 20V-813

Components:

POWER TRAIN: MANUAL TRANSMISSION: INTERNAL: GEARS

Potential Number of Units Affected: 2,285

Problem Description:

Yamaha Motor Corporation, USA (Yamaha) is recalling certain 2016-2020 Yamaha FJR13A and FJR13AE motorcycles. The second gear of the transmission can crack and break under high speed loads.

Consequence:

A broken gear can cause the transmission and rear wheel to lock causing a loss of control and increasing the risk of a crash.

Remedy

Yamaha will notify owners, and dealers will inspect and, as necessary, reprogram the Engine Control Unit (ECU) and replace the main axle and drive axle assemblies, free of charge. The recall is expected to begin January 13, 2021. Owners may contact Yamaha customer service at 1-800-962-7926. Yamaha's number for this recall is 990141. Note: Owners are advised not to operate their motorcycle until the repairs have been performed.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received Yamaha's proposed owner notification letter and envelope and approved them for distribution.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SS

20V-813

Please ensure the following requirements are met:

Please amend your 573 to include the information that owners are advised not to ride their motorcycle until the recall remedy has been performed.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Shiver who may be reached by phone at (202) 366-7401, or by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,

Joshua Neff

Chief, Recall Management Division Office of Defects Investigations

Enforcement

