OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-022

Manufacturer Name: Keystone RV Company

NHTSA Recall No.: 21V-022

Manufacturer Recall No.: 21-400



Manufacturer Information:

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN

46527

Company phone: 574-535-2100

Population:

Number of potentially involved: 12 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2021-2021 Dutchmen Voltage 3915, 4225

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Model(s) 3915, 4225

Production Dates: JAN 04, 2021 - JAN 11, 2021

VIN Range 1: Begin: 4YDF39130MZ990693 End: 4YDF42238MZ990721 ✓ Not sequential

Description of Defect:

Description of the Defect: It has been decided that the vehicles in the recall population fail to conform to

the requirements of Part 567, "Certification." The vehicles subject to this recall may have been manufactured with the incorrect information on the Federal Identification Tag. The tag indicates the tire pressure as 95 PSI. The correct tire

pressure is 110 PSI.

FMVSS 1: 567 - Certification

FMVSS 2: NR

Description of the Safety Risk: An incorrect label may lead to unintentionally underinflating the tires,

increasing the risk of a crash.

Description of the Cause: The incorrect tire pressure information was printed on the label

Identification of Any Warning PSI on the Federal Identification Tag does not match information for the rim

that can Occur: and tire.

Involved Components:

Component Name 1: Fed Tag

Component Description: Label - Tread Gen Fed Cert Combo Laser - 9/05 - FD316

Component Part Number: 192406

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

01/13/2021 – Report was made by engineering that the FED ID tag info was incorrect for the tire PSI. 1/18/2021 – Range and Scope completed.

Description of Remedy:

Description of Remedy Program: The remedy is to replace the Federal Identification Tag. Manufacturer

Reimbursement Plan on file as of 10/07/2020. General reimbursement plan to be updated every two years. New vehicles are covered under

warranty.

How Remedy Component Differs The repair will conform to requirements of Part 567, "Certification."

from Recalled Component:

Identify How/When Recall Condition Units were quarantined, inspected then repaired as indicated by

was Corrected in Production: inspection.

Recall Schedule:

Description of Recall Schedule: Keystone will notify the dealers of the recreational vehicles by letter.

There are no owners involved as all inventory is with dealers. A final copy of the dealer letter will be provided to NHTSA, along with the dealer

anoin nuocadunas

repair procedures.

Planned Dealer Notification Date: FEB 18, 2021 - FEB 18, 2021

Planned Owner Notification Date: NR - NR

Part 573 Safety Recall Report	21V-022	Page 3
* NR - Not Reported		
The information contained in this report wa	s submitted pursuant to 49 CFR §573	