

The view below shows what it would like if the sensor cables are installed incorrectly. The sensor cables should not cross side to side.

