

Parts Bulletin

TITLE:

**Recall R10079 Polestar 2 Software Update
Model Year: Polestar 2 2021**

**GROUP:
30**

**NO:
R10079**

**CAR MARKET:
United States and Canada**

REVISIONS:

**ISSUE DATE:
2021-03-01**

**STATUS DATE:
2021-03-01**

Page 1 of 1

Reference Bulletins: QB R10079

Polestar on behalf of Polestar Performance AB, have decided to launch Recall R10079 on certain model year 2021 Polestar 2 vehicles.

Polestar has identified that there is a risk of a micro-processor reset in the Battery Energy Control Module (BECM) which may cause the High Voltage contactors to open during driving. During driving, without any initial warning, there may be a risk that the high voltage system becomes unintentionally disconnected.

Worst case scenario is loss of propulsion during driving leading to increased risk of crash and injury. Full steering and brake capability remain.

The corrective action is to perform a Software Upgrade. Either an authorized Polestar Service Point or an over-the-air ("OTA") download can be installed with the software update.

The following part numbers apply:

Part Number	Description	Qty
32292674	Software downloading according to QB R10079	1