

CAMPAIGN LAUNCH STATUS

N566- SAFETY RECALL- 20MY RR EVOQUE – DRIVER KNEE AIRBAG



SAFETY RECALL N566 – DRIVER SIDE KNEE AIR BAG REPLACEMENT

AFFECTED MODELS	20 MY Range Rover Evoque
VOLUME AFFECTED	250 USA and 66 Canadian
REPAIR	The driver side lower knee airbag module cushion cover may become loose due to a degradation of the adhesive on the airbag dust cover. This can result in the airbag cushion partially unfolding from the knee airbag module housing and being visible in the footwell. In a crash, the driver may not receive full protection. The lower airbag will be replaced.
REPAIR TIME	Est 0.2hrs+Drive in/out
CAMPAIGN LAUNCH	Target April 16 th 2021, when parts are available.
Notes	Retailers received notification bulletin (NAS21.03.030 USA and NAS21.03.029 CAN) on March 25 th 2021. All affected units are retailed. Owner mailing will commence by April 23 rd , 2021