

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 22, 2021

Ms. Terri Tobias Regulatory Compliance Manager Jayco, Inc. 903 South Main Street P.O. Box 460 Middlebury, IN 46540

Subject: Incorrectly Routed Furnace Hose May Cause Gas Leak

Dear Ms. Tobias:

This letter serves to acknowledge Jayco, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ENTEGRA/REATTA/2021 JAYCO/EMBARK/2021

Mfr's Report Date: March 16, 2021

NHTSA Campaign Number: 21V-180

Components:

EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:LPG SYSTEMS:FURNACE

Potential Number of Units Affected: 29

Problem Description:

Jayco, Inc. (Jayco) is recalling certain 2021 Jayco Embark, and Entegra Reatta Class A Motorhomes. The LP furnace hose may be routed incorrectly, which could restrict the gas flow, or cause chafing against surrounding components, resulting in a gas leak.

Consequence:

A gas leak in the presence of an ignition source can increase the risk of fire or explosion.

Remedy:

Jayco will notify owners, and dealers will remove the existing LP line, and install a new extended gas manifold, free of charge. The recall is expected to begin April 16, 2021. Owners may contact Jayco customer service at 1-800-517-9137. Jayco's number for this recall is 9903565.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107KL

21V-180

Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Jayco, Inc.'s contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

