

## Service Bulletin

21-039

March 26, 2021 Version 1

## Safety Recall: Multi-Model Fuel Pump Motor

## **AFFECTED VEHICLES**

Year	Model	Trim Level	VIN Range
2019-20	Accord 1.5T	ALL	Check the iN VIN status for eligibility.
2019	Accord Hybrid	ALL	Check the iN VIN status for eligibility.
2019	Civic 2-Door	ALL except Si (HCM, HMIN)	Check the iN VIN status for eligibility.
2019	Civic 4-Door	ALL except Si (HCM, HMIN)	Check the iN VIN status for eligibility.
2019-20	Civic 5-Door	ALL except Type R (HUM)	Check the iN VIN status for eligibility.
2019	Civic Type R	ALL	Check the iN VIN status for eligibility.
2018-19	CR-V	ALL	Check the iN VIN status for eligibility.
2019	Fit	ALL	Check the iN VIN status for eligibility.
2019	HR-V 2WD	ALL	Check the iN VIN status for eligibility.
2019	HR-V AWD	ALL	Check the iN VIN status for eligibility.
2019	Odyssey	ALL	Check the iN VIN status for eligibility.
2019	Passport	ALL	Check the iN VIN status for eligibility.
2019	Pilot	ALL	Check the iN VIN status for eligibility.
2019	Ridgeline	ALL	Check the iN VIN status for eligibility.

## **BACKGROUND**

Due to swelling of the fuel pump motor impeller, the fuel pump may seize and stop working. If this occurs, the check engine light may be displayed with DTC P0087 (Fuel Rail Pressure Too Low) stored, the engine may not start, or the engine could stall while driving, increasing the risk of a crash.

If this temporary placeholder bulletin appears during an iN VIN status inquiry, this vehicle is subject to a Safety Recall. This vehicle is on **STOP SALE** until further notice. Check for an iN message for further details. Refrain from calling Tech Line for updates.

This bulletin will be updated once Parts Information, Warranty Claim Information, Inspection Procedures, and Repair Procedures are available.

**END** 

**CUSTOMER INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.