AUDI DEALER COMMUNICATION ibu

Advance Notice – Safety Recall 10G9 / Engine Block Casting

This notice is for: Date:	 ✓ Dealer F ✓ General ✓ Sales Ma May 19, 202 	anagers	 ✓ Service Ma ✓ Parts Mana ✓ Service Adv 	nager ✓ W Iger ✓ Te visor	arranty Administrator echnicians
Issue:	Due to a process error that occurred during the engine block casting process, it is possible for cracks to develop on the running surface of the 'cylinder 6' bore. During engine operation, a crack in the bore can lead to an impaired contour of the piston's running surface. If this occurs, there is potential for engine damage and oil leakage. Engine damage while driving may cause a loss of power or an engine stall, increasing the risk of a crash.				
Precautions	If this condition is present in the vehicle, possible noises from the engine crankshaft may occur while driving and an oil pressure warning may be displayed in the instrument cluster.				
Repair:	REPAIR NOT YET AVAILABLE Check daily campaign open inventory report or OMD for affected vehicles in inventory. Beginning Ending Vehicle Vehicle				
Affected Vehicles	Country			Vehicle	
Affected Vehicles	Country	Model Year	Model Year		Count
Affected Vehicles	USA	Model Year 2021	Model Year 2021	RS6 AVANT	Count 2
Affected Vehicles	USA USA	Model Year 2021 2021	Model Year 2021 2021	RS6 AVANT RS7	Count 2 4
Affected Vehicles	USA USA USA	Model Year 2021 2021 2021 2021	Model Year 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8	Count 2 4 1
Affected Vehicles	USA USA USA USA	Model Year 2021 2021 2021 2021 2021 2021	Model Year 2021 2021 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8 SQ7	Count 2 4 4 1 5
Affected Vehicles	USA USA USA USA USA	Model Year 2021 2021 2021 2021 2021 2021 2021 2021	Model Year 2021 2021 2021 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8 SQ7 SQ8	Count 2 4 1
Affected Vehicles	USA USA USA USA USA CAN	Model Year 2021 2021 2021 2021 2021 2021 2021 2021 2021 2021	Model Year 2021 2021 2021 2021 2021 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8 SQ7	Count 2 4 4 1 5
Affected Vehicles	USA USA USA USA USA	Model Year 2021 2021 2021 2021 2021 2021 2021 2021	Model Year 2021 2021 2021 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8 SQ7 SQ8	Count 2 4 4 1 5 5 3
Affected Vehicles	USA USA USA USA USA CAN	Model Year 2021 2021 2021 2021 2021 2021 2021 2021 2021 2021	Model Year 2021 2021 2021 2021 2021 2021 2021 2021 2021	RS6 AVANT RS7 RSQ8 SQ7 SQ8 RS6 AVANT	Count 2 4 4 1 5 3 3 2

campaign inquiry & verification source.

Notes:

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.