

May 21, 2021

Mr. Kerry Legg Vehicle Safety and Regulatory Compliance Manager Motor Coach Industries 711 Kernaghan Avenue Winnipeg, MB Canada R2C 3T4

Subject: High Pressure Fuel Rail Assembly May Leak Fuel

Dear Mr. Legg:

This letter serves to acknowledge Motor Coach Industries's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MCI/D4000/2017-2018 MCI/D4000ISTV/2017-2019 MCI/D4005/2017-2019 MCI/D45 CRT LE/2018-2020 MCI/D4500/2017-2020 MCI/D4505/2017-2019 MCI/J3500/2018-2021 MCI/J4500/2017-2020

Mfr's Report Date: May 18, 2021

NHTSA Campaign Number: 21V-364

Components:

FUEL SYSTEM, DIESEL:FUEL INJECTION SYSTEM:FUEL RAIL

Potential Number of Units Affected: 1,853

Problem Description:

Motor Coach Industries (MCI) is recalling certain 2017-2018 D4000, 2017-2019 D4005, D4000ISTV, D4505, 2017-2020 D4500, J4500, 2018-2020 D45CRTLE, and 2018-2021 J3500 vehicles. The sealing washer may not seat correctly in the pilot bore holes, allowing the high pressure fuel rail assembly to leak.

Consequence:

A fuel leak in the presence of an ignition source increases the risk of a fire.

Remedy:

Dealers will inspect the rail threads, and replace the rail as necessary, free of charge. Owner notification letters are expected to be mailed May 31, 2021. Owners may contact MCI customer service at 1-800-241-2947. MCI's number for this recall is R21-009.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107MR 21V-364

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

We have received MCI's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Motor Coach Industries's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Lee And

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

