

**December 2021**  
**FL888 (D21R7)**  
**NHSTA #21V-369 (Non School)**  
**NHTSA #21V-370 (School Bus)**  
**Transport Canada #2021-304 (Non School)**  
**Transport Canada #2021-325 (School Bus)**

**Recall Notification**  
**Subject: Tie Rod Clamp (Lock Nut) Over-Crimped**  
**Tie Rod End Clamp Bolts**

Daimler Trucks North America has notified its dealers and customers in the U.S. and Canada of a safety related defect that exists in certain chassis manufactured by Freightliner Custom Chassis Corporation and delivered to your company. A remedy without charge is now available, and owners may take their vehicle to a Daimler Trucks-authorized service facility to have the recall performed. The recall bulletin, owner notification letters, and a list of potentially affected vehicles delivered to you are attached for your information.

Your company may have an obligation to notify its dealers, distributors, and customers of this recall under Title 49 Code of Federal Regulations Part 577.13 and/or Motor Vehicle Safety Act Section 10(1). Companies that did not provide their affected make(s) and model(s) will be required notify Canadian customers under Canadian regulations.

If you have questions or need further information, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time.

WARRANTY CAMPAIGNS DEPARTMENT  
Enclosure