

CAMPAIGN LAUNCH STATUS



N598 RECALL 20-22MY DEFENDER - INOPERATIVE REAR LAMPS

SAFETY RECALL N598 REAR LAMPS MAY NOT OPERATE			
AFFECTED MODELS	20-22MY Defender X model fitted with 'smoked' rear lamps		
VOLUME AFFECTED	2785 USA 274 CAN		
REPAIR	Should an intense light source shine directly on the rear of an affected vehicle at a certain angle, the stop, turn signal and/or tail lamp may experience an over-voltage event, and cease to function. Both rear lamp assemblies will be replaced to rectify this.		
REPAIR TIME	c 1.7 hrs + Drive in/out		
TARGET CAMPAIGN LAUNCH	TBC		
Notes	A new design of lamp has been approved and the supplier is commencing manufacture. Supply restrictions for semi conductors will increase lead times with recall launch quantities of lamps currently not expected in market before late August.		



PRINTED COPIES ARE UNCONTROLLED