

CAMPAIGN LAUNCH STATUS

N598 RECALL 20-21MY DEFENDER - SMOKED REAR LAMPS



SAFETY RECALL N598 REAR LAMPS MAY NOT OPERATE

AFFECTED MODELS	20-21MY Defender X model fitted with 'smoked' rear lamps
VOLUME AFFECTED	2785 USA 274 CAN
REPAIR	Should an intense light source shine directly on the rear of an affected vehicle at a certain angle, the stop, turn signal and/or tail lamp may experience an over-voltage event, and cease to function. Both rear lamp assemblies will be replaced to rectify this.
REPAIR TIME	c 2.0 hrs + DIDO
TARGET CAMPAIGN LAUNCH	Late August 2021
Notes	Initial supplies of new lamps are now being received in market. Recall will launch when there are sufficient stocks and with a requirement to order replacement parts by VIN. Priority should be given to customer vehicles rather than stock.



PRINTED COPIES ARE UNCONTROLLED