

CAMPAIGN LAUNCH STATUS

N598 RECALL & N609 RECALL



SAFETY RECALL N598 REAR LAMPS MAY NOT OPERATE	
AFFECTED MODELS	20-21MY Defender X model fitted with 'smoked' rear lamps
VOLUME AFFECTED	2786 USA 274 CAN
REPAIR	Should an intense light source shine directly on the rear of an affected vehicle at a certain angle, the stop, turn signal and/or tail lamp may experience an over-voltage event, and cease to function. Both rear lamp assemblies will be replaced to rectify this.
REPAIR TIME	c 2.0 hrs + DIDO
CAMPAIGN LAUNCHED	August 23 rd , 2021
Notes	Limited Initial supplies of new lamps received in market. To support launch, there is a requirement to order replacement parts by VIN. Priority should be given to customer vehicles rather than stock.

SAFETY RECALL N609 FRONT SEAT TRACK – DEFENDER 90	
AFFECTED MODELS	21MY Defender 90 with manual seats
VOLUME AFFECTED	603 USA 66 CAN
REPAIR	Vehicles with manually adjustable front seats, the front seat track end stop bracket may become deformed. Deformed seat track end stop brackets may allow the seat to latch further forward than intended by design and may allow reduced seat strength in the event of a crash. Both front seats on affected vehicles will require replacement of the seat tracks with a modified part.
REPAIR TIME	1.0 hrs + DIDO
TARGET CAMPAIGN LAUNCH	Retailer recall notification and stop sale July 15 th , 2021. NAS21.07.017 CAN and NAS21.07.018 USA Repair publication awaiting additional parts stock.
Notes	25 unsold units in retailer stock. Requires locally sourced Loctite 243 thread lock