

Part 573 Safety Recall Report

21V-456

Manufacturer Name : Terex Advance Mixer, Inc.**Submission Date :** JUN 17, 2021**NHTSA Recall No. :** 21V-456**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Terex Advance Mixer, Inc.

Address : 7727 Freedom Way
Fort Wayne IN 46818

Company phone : 999

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2021-2021 Front Discharge Mixer Commanders & Chargers

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

Descriptive Information : The shaft key for the chute swing motor was not installed properly.

Production Dates : FEB 22, 2021 - MAY 05, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : It was found that a specific operator was not installing the set screw on the chute swing gear boxbox output shaft. This could lead to the keyway falling out. This will allow the chutes to swing freely.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The chutes could swing freely which could result in personal or property damage.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :**Involved Components :**

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported