
AMB3 Recall Campaign - Replacing seat occupancy detection system for passenger seat



English (US)

- Overview on page 2
- Parts required on page 2
- Warranty processing on page 2
 - Scope 1: 18-way sports seat without fire extinguisher on page 3
 - Scope 2: 14-way comfort seat without fire extinguisher on page 3
 - Scope 3: 18-way sports seat with fire extinguisher on page 3
 - Scope 4: 14-way comfort seat with fire extinguisher on page 3
- · Porsche Mobility on page 3

AMB3 Recall campaign - Replacing seat occupancy detection system for passenger seat

1

Overview

Due to an incorrect parts list, the affected vehicles were fitted with a passenger seat variant that is not approved for the relevant market.

As a result, it is possible that the electrical signal in the passenger seat is insufficient to correctly recognize certain occupants in the passenger seat. In some cases, this may interrupt the triggering of the restraint systems on the passenger side. This is alerted to the driver

by an airbag warning light or "Passenger Airbag OFF" light which is activated.

Therefore, the components for the seat occupancy detection system in the passenger seat must be replaced.

Within the market area for which you are responsible, please arrange for this measure to be carried out on the affected vehicles immediately.

Model type 911 Carrera (992)

Model year 2021 Number 142

Parts required

Part number	Designation	Quantity/vehicle	Parts return request*
992881256N	Repair kit for seat oc- cupancy detection sys- tem (18-way sports seat passenger's side)	1	No
992881256K	Repair kit for seat oc- cupancy detection sys- tem (14-way comfort seat passenger's side)	1	No
992898054A	Set of small parts	1	No

^{*}The parts must be stored in WWS until **the relevant warranty/campaign claim** has been settled (credit note). If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Warranty processing

Please enter the completed campaign into the Guarantee and Maintenance booklet of the vehicle.

Scope 1: 18-way sports seat without fire extinguisher

Damage Code AMB3 99 000

Repair Code 2

Working time 231 TU

Scope 2: 14-way comfort seat without fire extinguisher

Damage Code AMB3 99 000

Repair Code 2

Working time 231 TU

Scope 3: 18-way sports seat with fire extinguisher

Damage Code AMB3 99 000

Repair Code 2

Working time 257 TU

Scope 4: 14-way comfort seat with fire extinguisher

Damage Code AMB3 99 000

Repair Code 2

Working time 257 TU

Porsche Mobility

If requested, the mobility of the affected customer can be guaranteed by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.