

U.S. Department of Transportation

National Highway Traffic Safety Administration

July 13, 2021

Mr. Dennis Postiy Corporate Vice President Mac Trailer Mfg., Inc. 14599 Commerce Street Alliance, OH 44601

Subject: Steering Arm May Detach

Dear Mr. Postiy:

This letter serves to acknowledge Mac Trailer Mfg., Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

#### Makes/Models/Model Years:

MAC TRAILERS/DUMP TRAILER/2017-2020

Mfr's Report Date: July 1, 2021

NHTSA Campaign Number: 21V-501

## **Components:**

**STEERING** 

STEERING:LINKAGES:KNUCKLE:SPINDLE:ARM

**Potential Number of Units Affected:** 53

#### **Problem Description:**

Mac Trailer Mfg., Inc. (Mac Trailer) is recalling certain 2017-2020 Dump trailers equipped with Ingersoll Smart-Steer self steer axles. The steering arm may detach from the steering knuckle during certain low-speed, high-side loading maneuvers.

# **Consequence:**

A detached steering arm may cause a loss of steering control. In addition, attachment hardware may fall and become a road hazard. Both of these scenarios can increase the risk of a crash.

## Remedy:

Dealers will inspect the steering arm and apply welds, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Mac Trailer customer service at 1-330-823-9900.

# Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR

21V-501

## Please ensure the following requirements are met:

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

## AMENDED 573 REQUIRED.

Your company's program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of your company's notification of owners, purchasers and dealers, in accordance with § 573.13. Your company's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by § 573.13 that is not in a general reimbursement plan shall be submitted in your company's report to NHTSA. If your company submits one or more general reimbursement plans, your company shall update each plan every two years (§ 573.13). If the vehicles are new and would be covered under the manufacturer's warranty program, please state that in the remedy section of your filing.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mac Trailer Mfg., Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

