



## IMPORTANT SAFETY RECALL NOTICE

### NHTSA Recall No. 21V-561

9/1/2021

[REDACTED]  
[REDACTED]  
[REDACTED]

This important safety recall notice applies to your vehicle with the following Vehicle Identification Number (“VIN”):

[REDACTED]

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

McLaren Automotive Incorporated (“**McLaren**”) has decided that a defect that relates to motor vehicle safety exists in certain Model Year 2019 – 2020 McLaren vehicles. According to our records, you are the owner of one of those vehicles.

#### WHAT IS THE ISSUE?

McLaren has determined that the banjo bolt that is fitted between the flexi-hose and the caliper within the brake assembly on each corner of the vehicle may not function properly. The banjo bolt is designed to include holes to allow the passage of hydraulic fluid to the brake caliper. However, the banjo bolts fitted on some of the brake assemblies may not have had the holes drilled into them. If this occurs, there would be no hydraulic pressure to the calliper, and there would be no braking effect on the affected corner of the vehicle.

This could result in the vehicle pulling to one side under braking, particularly when braking from a high speed, which could increase the risk of a crash.

#### WHAT McLAREN WILL DO

To remedy this problem, your McLaren dealer will disassemble the brake hose assembly on each corner of the vehicle, remove the banjo bolt and inspect it. In the event the banjo bolt is defective, it will be replaced. The brake hose assembly will then be reassembled, and the brakes bled.

**This remedy will be performed at no cost to you.**



## WHAT YOU SHOULD DO

At your earliest convenience, please call your McLaren dealer to schedule an appointment to have the remedy performed. We estimate that the procedure will take up to two (2) hours to complete.

We recommend that you do not use the vehicle for any track use until the remedy has been performed.

## OTHER IMPORTANT INFORMATION

If you no longer own the vehicle identified above, please contact McLaren's Client Services department at (855) 202-8815 or [clientservicesna@mclaren.com](mailto:clientservicesna@mclaren.com). If possible, please provide us with the name and address of the current owner so we may contact him or her regarding this recall.

If you have any questions or require further assistance, please contact McLaren's Client Services department at (855) 202-8815 or [clientservicesna@mclaren.com](mailto:clientservicesna@mclaren.com).

If you believe that McLaren has failed or is unable to remedy the defect without charge within a reasonable time, please contact us at the number shown above. You may also contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you have leased any of the above-referenced vehicles to another person, Federal regulations require you to send a copy of this notice to the lessee by first-class mail within ten days of your receipt of this notice.

Thank you for your prompt attention to this matter. We sincerely regret any inconvenience that this condition may cause you. Your safety is our highest priority.

Sincerely,