



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 11, 2021

Lisa Sampson
Rosenbauer America
100 3rd St
Lyons, SD 57041

NEF-107MR
21V-562

Subject: Weight and Tire Pressure Incorrect /FMVSS 567

Dear Lisa Sampson:

This letter serves to acknowledge Rosenbauer America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

ROSENBAUER/COMMANDER/2012-2016
ROSENBAUER/WARRIOR/2012-2016

Mfr's Report Date: July 23, 2021

NHTSA Campaign Number: 21V-562

Components:

EQUIPMENT:OTHER:LABELS

Potential Number of Units Affected: 360

Problem Description:

Rosenbauer America (Rosenbauer) is recalling certain 2012-2016 Commander and Warrior vehicles. The vehicle weight and tire pressure information may be incorrect on the certification label. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 567, "Certification."

Consequence:

Incorrect tire pressure information can result in underinflated tires, increasing the risk of a crash.

Remedy:

The remedy is currently under development. Owner notification letters are expected to be mailed September 8, 2021. Owners may contact Rosenbauer customer service at 1-651-462-1000.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

An identification and description of the risk to motor vehicle safety reasonably related to the defect or noncompliance (49 CFR 573.6 (c)(5)). All filings should state an increased risk of either a crash, injury or fire.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Rosenbauer America's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement