

MACK TRUCKS RECALL ALERT



Subject: Safety Recall SC0427, Rear Rear Brake Insp
Recall Number: SRA-M427
Date: July 30, 2021

Applicable Markets: U.S. Canada

Description

Mack has determined that certain model year 2021 trucks equipped with Meritor drum brakes may have the incorrect brake cams installed on the rear most drive axle. The rear rear axle brakes may be inoperative, which can result in increased stopping distances and potential risk of a vehicle crash.

The wheels and drums on the rear most axle will need to be removed to gain access to the brake cams for inspection. If the brake cams are found to be correct, reassemble the unit and no further action is required. If the brake cams are found to be incorrect, replacement of the brake cams, brake shoes, brake hardware, and wheel seals may be required.

Model and Model Years Affected

- Certain Mack 2021 Granite, LR and TerraPro model vehicles; Build dates: June 29, 2020 through September 22, 2020.

Vehicle Quantities

- 124 (all US)

Dealer Responsibilities

- The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to ensure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer.
- Dealers should make their personnel aware of the safety recall. In the event that a dealer has a vehicle included in the safety recall in their inventory to be sold, the condition must be corrected before releasing it to a customer.

Notification Release Schedule

- Vehicle list will be posted on the Trucks Dealer Portal on July 30, 2021.
- Owner notification letters will be released on or before August 27, 2021.

Contact

If you have questions or concerns about this recall, contact the Regulatory Affairs Department at vtna.regulatoryaffairs@volvo.com.