

CAMPAIGN LAUNCH STATUS

N601 SAFETY RECALL – OWNER HANDBOOK CORRECTION



SAFETY RECALL N601 – OWNER HANDBOOK CORRECTION TO CHILD SEAT LATCH ANCHORS

| | |
|-----------------|---|
| AFFECTED MODELS | 20-21MY Defender with 3 rd Row Seating. |
| VOLUME AFFECTED | 7027 USA and 427 Canada |
| REPAIR | On certain vehicles equipped with third row seats, the owner's manual incorrectly states that the third-row seating is installed with LATCH child seat fixings with top tethers. The owner manual requires an update to insert a printed supplement correcting the error. |
| REPAIR TIME | 0.1hrs to insert supplement in handbook+ Drive in/out |
| CAMPAIGN LAUNCH | Launched September 15th, 2021 |
| Notes | Unsold vehicles to be repaired by retailers. Owners of all sold vehicle were mailed a handbook supplement on Sept 23rd, 2021. Those VIN will now be closed in the recall. |



PRINTED COPIES ARE UNCONTROLLED