



Dear Slingshot Owner,

Our records indicate that you are the owner of a Slingshot affected by Safety Recall **T-21-01** that was announced on Friday 13, 2021.

Polaris has decided that a defect which relates to motor vehicle safety exists in 2020-2021 Slingshot vehicles. Slingshot vehicles may have rear wheel studs that were not pressed into the axle fully during the supplier's assembly process. An improperly installed rear wheel stud could lead to loosening of the rear lug nuts, resulting in a loose or detached rear wheel during operation, increasing the risk of a crash.

This recall has been released to instruct dealers to complete the outlined inspection to identify any improper axle assemblies and replace if necessary. This work will be performed by your dealer at no cost to you.

Visit our [On-Road Safety Recall page](#) to verify if your Slingshot is impacted by the recall. Contact your dealer to schedule a service appointment or complete a transfer of ownership if you no longer own the vehicle. Your local POLARIS dealer can be found on our [Dealer Locator](#) page.

While your dealer is in the best position to answer your questions, you can also call our Polaris Owner Connections Department at: **1-800-POLARIS (1-800-765-2747)** to speak with a representative.

Sincerely,

Polaris Service

This email was sent to you by Polaris Slingshot because you are a registered owner of a Slingshot vehicle affected by a recent service announcement. Please do not reply to this email.