#### The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Manufacturer Name :Custom Fire Apparatus, Inc.Submission Date :AUG 09, 2021NHTSA Recall No. :21V-630Manufacturer Recall No. :21009 (21V-323)

### Manufacturer Information :

Manufacturer Name : Custom Fire Apparatus, Inc. Address : 509 68th Ave Osceola WI 54020 Company phone : 294-2555

### Vehicle Information :

Vehicle 1:	2017-2021 Spartan Gladiator MetroStar MetroStarX	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	UNKNOWN	
Power Train :	DIESEL	
Descriptive Information :	Problems with Cummins Engines models L9 and X12	
Production Dates :	JAN 02, 2017 - AUG 02, 2021	
VIN Range 1:	Begin : 4S7CU2D9XKC086603 End : 4S9CU2D98LC560119 📝 Not sequential	

## **Description of Defect :**

Description of the Defect :	On the affected vehicles, the fuel rail assembly may develop leaks, which may result in an undetected prolonged diesel fuel spray.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.
Description of the Cause :	NR
• •	The operator may see or smell diesel fuel. In some cases, the check engine lamp may illuminate.

### **Involved Components :**

Population :

Number of potentially involved :48Estimated percentage with defect :100 %



21V-630

## Part 573 Safety Recall Report

Component Name 1 : Engine Component Description : NR Component Part Number : NR

### **Supplier Identification :**

### **Component Manufacturer**

Name : Spartan Fire LLC Address : 1541 Reynolds Road Charlotte Michigan 48813 Country : United States

### **Chronology**:

NR

### **Description of Remedy :**

Description of Remedy Program :	Cummins will instruct you to take your vehicle to a Cummins authorized service center to inspect the fuel rail. If damage is found, the fuel rail and fuel lines will be replaced. If no damage is found, the fuel rail will be reassembled with new crush washers using a special tool. There is no cost to the vehicle owner for the recall remedy.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

### **Recall Schedule :**

Description of Recall Schedule :	Cummins is notifying affected customers
Planned Dealer Notification Date :	AUG 09, 2021 - AUG 13, 2021
Planned Owner Notification Date :	AUG 09, 2021 - AUG 13, 2021

\* NR - Not Reported