

CAMPAIGN LAUNCH STATUS

N623 SAFETY RECALL – RR SPORT & LR4 FUEL TANK LEAK



SAFETY RECALL N623 - FUEL LEAKING FROM TANK OUTLET PIPE FLANGE	
AFFECTED MODELS	10-13MY Range Rover Sport and 10-16MY LR4
VOLUME AFFECTED	111,746 USA
REPAIR	Customers have reported fuel odor, occasionally liquid fuel on the ground. Retailers have diagnosed cracked fuel outlet pipe flange which will be replaced with a part of revised design. Any vehicles diagnosed with this concern today should be repaired following current processes and parts. The recall will remain open.
REPAIR TIME	1.2 hrs + Drive in/out
CAMPAIGN LAUNCH TARGET	TBC
Notes	Parts are being procured to support recall repair launch. Additional current parts to support interim repairs for leaking fuel tanks are being procured. Initial Owner notification October 8 th .2021. Recall Claims must not be submitted until the recall repair is published.