#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 21V-643

**Manufacturer Name:** Swab Wagon Company, Inc.

Submission Date: NOV 11, 2021 NHTSA Recall No.: 21V-643

**Manufacturer Recall No.:** NR



### **Manufacturer Information :** Population :

Manufacturer Name: Swab Wagon Company, Inc.

Address: 44 S. Callowhill St.

P.O. Box 919 Elizabethville PA 17023

Company phone: 362-8151

Number of potentially involved : 4 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2019-2019 Ford F-350 Super Cab

Vehicle Type: LOW VOLUME VEHICLES

Body Style : Power Train : NR

Descriptive Information: This recall involves the Code 3 #79STTRBZ 7" x 9" combination LED stop/tail/turn/

back-up lamps installed on several Swab Pioneer medic bodies. Our Code 3 invoices show the number of vehicles we installed these lights on, and who those vehicles are

owned by.

Production Dates: OCT 01, 2019 - OCT 30, 2019

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2018-2018 Chevrolet 3500 HD Double Cab

Vehicle Type: LOW VOLUME VEHICLES

Body Style : Power Train : NR

Descriptive Information: This recall involves the Code 3 #79STTRBZ 7" x 9" combination LED stop/tail/turn/

back-up lamps installed on several Swab Pioneer medic bodies. Our Code 3 invoices show the number of vehicles we installed these lights on, and who those vehicles are

owned by.

Production Dates: AUG 01, 2018 - AUG 31, 2018

Vehicle 3:	2019-2019 Chevrolet 3500HD Crew Cab				
Vehicle Type :					
Body Style :					
Power Train:	IR				
· 1	This recall involves the Code 3 #79STTRBZ 7" x 9" combination LED stop/tail/turn/back-up lamps installed on several Swab Pioneer medic bodies. Our Code 3 invoices show the number of vehicles we installed these lights on, and who those vehicles are owned by.				
<b>Production Dates</b> :	APR 01, 2019 - A	APR 30, 2019			
VIN Range 1:B	egin :	NR	End: NR	☐ Not sequential	
Vehicle 4: 2017-2017 Chevrolet 2500HD Regular Cab					
Vehicle Type :	LOW VOLUME VEHICLES				
Body Style :					
Power Train:	NR				
1	This recall involves the Code 3 #79STTRBZ 7" x 9" combination LED stop/tail/turn/back-up lamps installed on several Swab Pioneer medic bodies. Our Code 3 invoices show the number of vehicles we installed these lights on, and who those vehicles are owned by.				
Production Dates: APR 01, 2018 - APR 30, 2018					
VIN Range 1:B	egin :	NR	End: NR	☐ Not sequential	
Description of Noncompliance :					
-	•	The subject lamps exceed the maximum permissible candela levels specified in FMVSS No. 108 at certain test points.			
FMVSS 1: 108 - Lamps, reflective devices, an			ces, and assoc. E	quipment	
FMVSS 2: NR					
	of FMVSS 10 increasing th	ne increased photometric intensity does not comply with the requirements FMVSS 108 and may adversely affect the vision of following drivers, creasing the risk of a vehicle crash without warning.			
Description of the Cause : The lamps do not meet the requirements of the relevant standard				the relevant standard.	
Identification of Any Warning that can Occur					
Involved Components :					

Component Name 1: Code 3 7x9 Stop-Tail-Turn-Reverse All-in-One LED

Component Description: 7" x 9" LED combination stop/tail/turn/back-up light

Component Part Number: 79STTRBZ

#### **Supplier Identification:**

#### **Component Manufacturer**

Name: ECCO Holdings Corp. (Code 3)

Address: 833 West Diamond

Boise Idaho 83705

**Country: United States** 

#### **Chronology:**

Swab Wagon Company was notified by NHTSA on August 16th, 2021, that we had purchased and installed lighting from Code 3 that was noncompliant with FMVSS 108, and are required to conduct a formal recall to notify the owners of those vehicles. None of our customers filed warranty claims. On August 26, 2021, we proactively sent out filter kits provided to us by Code 3, Inc., free of charge, to our customers with the affected lighting equipment, which included instructions to the customer on how to properly install the filter kit. We have not been notified of any injuries or deaths associated with this noncompliant lighting equipment.

#### **Description of Remedy:**

Description of Remedy Program: Customers are to contact Code 3 Technical Support at (314)-996-2800 and

request a filter kit, Part No. CZ0199, which will be sent to them free of charge by Code 3. Installation of the filter kit will ensure that the lamps perform within the permissible photometric intensity ranges. We did not deem there to be any reason to reimburse the customers for anything as installation of the filter kits should only take, at most, two minutes of their time. No tools or automotive repair experience would be required to

install the filter kits.

How Remedy Component Differs The remedy involves installation of a filter kit that will ensure that the

from Recalled Component : lamps perform within the permissible photometric intensity ranges.

Identify How/When Recall Condition Code 3 discontinued production of the noncompliant lamps on March 27, was Corrected in Production: 2020 as part of a planned supplier changeover. The new, compliant lamps

will be assigned Part No. 79STTRBZ-D

#### **Recall Schedule:**

Description of Recall Schedule: We will notify any dealers who were involved with the sale of these

vehicles, as well as the vehicle owner's at the time of delivery. Should the vehicle no longer be owned by the original owner, we will obtain current vehicle ownership information and send them the recall notification.

Planned Dealer Notification Date : AUG 17, 2021 - AUG 20, 2021 Planned Owner Notification Date : AUG 17, 2021 - AUG 20, 2021

\* NR - Not Reported