OMB Control No.: 2127-0004

Part 573 Safety Recall Report

21V-803

Manufacturer Name: Provan Industries, LLC

Submission Date: OCT 14, 2021 NHTSA Recall No.: 21V-803 Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Provan Industries, LLC

Address: 4837 Edmund Hwy.

West Columbia SC 29170

Company phone: 803-955-3001

Population:

Number of potentially involved : 13 Estimated percentage with defect : 50 %

Vehicle Information:

Vehicle 1: 2019-2020 Tiger Adventure Vehicle Bengal TX

Vehicle Type: LOW VOLUME VEHICLES

Body Style : Power Train : NR

Descriptive Information: Our records show that this recall potentially affects 13 Bengal campers produced

between 09/19 and 01/21 with OPIM numbers 1310B- 1322B.

Production Dates: SEP 01, 2019 - JAN 01, 2021

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Defect:

Description of the Defect: Lippert Components has determined that some window vents may experience

an issue with the window adhesive bonding.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Inner and outer glass panes may become separated.

Description of the Cause: NR
Identification of Any Warning NR
that can Occur:

Involved Components:

Component Name 1: Window vent

Component Description: Galley window front vent

Component Part Number: 6402-40-P SVD 54.7 X 081 G20 TP BK 4.000 RADII

Component Name 2: Window vent

Component Description: Galley window rear vent

Component Part Number: 6402-40-R SVD 54.7 X 081 BK TP G20 4.000 RADII*

Component Name 3: Window vent

Component Description: Couch window front vent

Component Part Number: 6402-40-R SVD 58.7 X 081 G20 TP BK 4.000 RADII

Component Name 4: Window vent

Component Description: Couch window rear vent

Component Part Number: 6402-40-P SVD 58.7 X 081 BK TP G20 4.000 RADII

Supplier Identification:

Component Manufacturer

Name: Lippert Components Address: 88704 Expedite Way.

Chicago Illinois 60695

Country: United States

Chronology:

NR

Description of Remedy:

Description of Remedy Program: Provan RV Industries will send an inspection gauge along with recall

instructions to the potentially affected Bengal owners. Lippert

Components will pay 0.4 hours labor to inspect the involved windows and/or 0.5 hours labor to replace any needed vent. Replacement parts are

readily available.

How Remedy Component Differs NR

from Recalled Component :

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

^{*} NR - Not Reported