| ТОРІС | ТҮРЕ | RECALL CODE | QUESTION | ANSWER | | | |
|----------------|------------------|----------------|--|--|----------------------------|-------------------------|---------|
| | | | | | | | |
| Safety | | | What vehicles are included in | Country | Beginning Model Year | Ending Model Year | Vehicle |
| Recall 19Q4 | Safety Recall | 19Q4 | Safety Recall 19Q4? | USA | 2022 | 2022 | TIGUAN |
| | | | What is the safety concern for Safety Recall 19Q4? Are there any precautions I should take because my vehicle is part of Safety Recall 19Q4? | The brake pipe nut at the right front wheel well may not be torqued to the proper specification. If the nut becomes loose, brake fluid may leak. This in turn can result in the vehicle requiring a longer braking distance, increasing the risk of a crash. Vehicle driver may see the brake warning light illuminate just after significant brake fluid loss. If this happens, owners are advised to contact an authorized Volkswagen dealer without delay to make arrangements to have the vehicle inspected/repaired. | | | |
| | | | What is the repair for Safety Recall 19Q4? When will the repair for Safety Recall 19Q4 be available? | To correct this defect, your authorized Volkswagen dealer will Inspect and, if necessary, torque the affected nut to the proper value. Repairs for this recall have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer. | | | |