

Part 573 Safety Recall Report

21V-857

Manufacturer Name : Tracker Marine, LLC

Submission Date : DEC 13, 2021

NHTSA Recall No. : 21V-857

Manufacturer Recall No. : RT-0001



Manufacturer Information :

Manufacturer Name : Tracker Marine, LLC

Address : 2500 E. Kearney
Springfield MO 65898

Company phone : 417-873-4555

Population :

Number of potentially involved : 380

Estimated percentage with defect : 10 %

Vehicle Information :

Vehicle 1 : 2022-2022 Ranger Trail T22RT178 ,T22RT178B ,T22RT188 ,T22RT188B ,
T22RT188P ,T22RT188PB ,T22RT198P ,T22RT198PB ,T22VS1665 ,T22VS1682 ,
T22VS1782 ,T22VS1782B

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Basis was determined by date of manufacture minus trailers we still had at the plant that could be inspected/corrected prior to shipment. There are a total of 380 potential units affected.

Production Dates : JUN 30, 2021 -OCT 27, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : Fenders may be improperly spaced which can cause tires to rub fenders.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Could cause premature wear on tires risking a blowout while underway.

Description of the Cause : Fenders improperly spaced causing tires to rub while trailer loaded.

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : FENDER,9X32X14,GALV,LOWERED

Component Description : Trailer Fender

Component Part Number : 310311

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

We had a customer report a rubbing tire which prompted further review on 11-1-2021. After further review, an additional stock trailer was found to have the same condition. We have opted to recall the trailers due to safety concerns.

Description of Remedy :

Description of Remedy Program : All potentially affected units will be checked to make sure there is 3/4 inch spacing from trailer frame. Customers will be instructed to take their trailer to any of our dealers for inspection/correction at no charge to the customer. If the customer has already corrected the concern, they can contact our customer service department for reimbursement.

How Remedy Component Differs
from Recalled Component : NR

Identify How/When Recall Condition
was Corrected in Production : Upon discovery of the concern, steps were added to manufacturing to make sure proper spacing on fenders.

Recall Schedule :

Description of Recall Schedule : Letters sent to customers (certified mail) on November 12, 2021. Dealers notified on November 12, 2021.

Planned Dealer Notification Date : NOV 12, 2021 - NOV 15, 2021

Planned Owner Notification Date : NOV 12, 2021 - NOV 15, 2021

* NR - Not Reported