

U.S. Department of Transportation

National Highway Traffic Safety Administration

December 6, 2021

Tiffani Torgeson Daimler Trucks North America, LLC 4747 N Channel Ave Portland, OR 97217 1200 New Jersey Avenue SE Washington, DC 20590

NEF-107MR 21V-921

Subject: Damaged Valve Stem May Cause Loss of Tire Pressure

Dear Tiffani Torgeson:

This letter serves to acknowledge Daimler Trucks North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FCCC/MBC/2018-2022

FCCC/MC/2017-2023

FCCC/MT55/2018-2022

FCCC/S2C/2018-2022

FCCC/S2G/2018-2022

FCCC/S2RV/2018-2022

FCCC/XBR/2018-2019

FCCC/XBS/2018-2020

FCCC/XCL/2017-2019

FCCC/XCM/2017-2022

FCCC/XCR/2017-2023

FCCC/XCS/2017-2022

Mfr's Report Date: November 23, 2021

NHTSA Campaign Number: 21V-921

Components:

TIRES:VALVE

Potential Number of Units Affected: 18,808

Problem Description:

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2019 Freightliner Custom Chass XCL, 2017-2022 XCM, XCS, 2017-2023 MC, XCR, 2018-2019 XBR, 2018-2020 XBS, 2018-2022 MBC, MT55, S2C, S2G, S2RV vehicles. The tire valve stem extension for the inner wheel may come into contact with the outer wheel rim opening and become damaged.

Consequence:

Damage to the valve stem extension may result in a loss of tire pressure of the inner wheel, increasing the risk of a crash.



Remedy:

Dealers will remove the inner valve stem extensions and stabilizers, free of charge. Owner notification letters are expected to be mailed January 21, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL912. Note: This recall supersedes and expands recall 20V-529 (FL-861). Vehicles previously repaired under 20V-529 will need to have the new remedy completed under this recall.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Daimler Trucks North America, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

