



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

December 21, 2021

Mr. Adrian Diaz  
Assistant Engineering Director Automotive Safety Office  
Ford Motor Company  
330 Town Center Drive  
Suite 500/5024  
Dearborn, MI 48126

NEF-107DM  
21V-980

**Subject:** Side Curtain Air Bag May Not Inflate Properly

Dear Mr. Diaz:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

FORD/MUSTANG/2021

**Mfr's Report Date:** December 16, 2021

**NHTSA Campaign Number:** 21V-980

**Components:**

AIR BAGS:SIDE/WINDOW:CURTAIN

**Potential Number of Units Affected:** 93

**Problem Description:**

Ford Motor Company (Ford) is recalling certain 2021 Mustang vehicles. The side curtain air bag inflators may have been manufactured with the incorrect amount of compressed gas, which can result in improper air bag inflation. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 226, "Ejection Mitigation," and 214, "Side Impact Protection."

**Consequence:**

An air bag that does not inflate properly can increase the risk of injury in a crash.

**Remedy:**

Dealers will replace the side curtain air bags, free of charge. Owner notification letters are expected to be mailed February 1, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C37.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please be reminded of the following requirements:



You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Under 49 U.S.C. § 30112(a), it is illegal for anyone, including a manufacturer, distributor, dealer, or retailer to sell an item of equipment or vehicle that fails to comply with all applicable Federal motor vehicle safety standards.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Ford Motor Company's contact for this recall will be DeMara Magruder who may be reached by email at [demara.magruder@dot.gov](mailto:demara.magruder@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement