



SAFETY RECALL

2021 CMX1100A/D - Radiator Cap Replacement

BACKGROUND

Honda is launching a **SAFETY RECALL** on **CERTAIN 2021 CMX1100A/D** vehicles to replace the radiator cap for a potential defect. If the vehicle is used continuously, hot coolant may leak from the radiator reservoir overflow tube or spay from the radiator cap, increasing the risk of crash or injury.

AFFECTED UNITS

CERTAIN NEW or USED 2021 CMX1100A/D.

To search for applicable recall on a specific unit, you **MUST** use *Unit Information* on **iN** available December 16, 2021.

To manage your affected inventory, use your dealer *eResponsibility Report* on **iN** available December 17, 2021.

DEALER INVENTORY

As of December 16, 2021, **YOU MUST NOT SELL** any affected **NEW OR USED** motorcycle in the **AFFECTED UNIT** section until it is repaired, according to this Service Bulletin.

- To search for applicable recalls on a specific unit, you must use *Unit Information* on **iN**, available December 16, 2021.
- To manage your affected inventory, refer to *eResponsibility Report* on **iN**, available December 17, 2021.

PARTS INFORMATION

Parts needed for the repair can be ordered according to the instructions in the forthcoming Service Bulletin.

REPAIR PROCEDURE

The complete Service Bulletin with repair procedure, parts information, as well as warranty claim information is expected to be available on **iN** by the end of business Thursday, December 23, 2021.

DEALER REPAIR RESPONSIBILITY

- Safety Recall repairs must be performed by a qualified technician.
- Installing the remedy parts exactly as shown in Repair Procedure instructions is critical for the recall remedy to be effective. Carefully follow all instructions.
- Service Management should inspect and confirm the repair.
- Dealer submission of a warranty claim affirms this safety recall was properly performed.