



Original Publication Date: December 21, 2023

To: All Lexus Dealer Principals, General Managers, Service Managers, and Parts Managers

EQUIPMENT SAFETY RECALL 22LH01

Defective Seatbelt Retractor Force Limiter

NHTSA Recall No. 22E-095

On November 10, 2022, Lexus filed an Equipment Safety Recall regarding certain front seat belt service parts distributed to Lexus dealers. Certain SC430, RX330, and RX350 vehicles have been identified that could potentially have defective seatbelts installed. These vehicles are now included in Equipment Safety Recall 22LH01.

- A component in the subject front seat belt assemblies may not have been manufactured properly and may cause the seat belt to not operate as designed. This can increase the risk of an injury in the event of certain types of crashes.
- Any authorized Lexus dealer will inspect the seat belt assembly and, if necessary, replace it FREE OF CHARGE.
- Equipment Safety Recall 22LH01 Dealer Letter and Technical Instructions now available on TIS.

Refer to the Dealer Letter and Technical Instructions on TIS for additional information.

Thank you for your cooperation.

LEXUS, A DIVISION OF TOYOTA MOTOR SALES, U.S.A., INC.